

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 8/26/2024 Time: 10:39 AM  
Name of School Corporation: NORTH WEST HENDRICKS SCHOOLS Corp ID: 323295  
Address of School Corporation: PO Box 70  
City: Lizton Zip: 46149 County Number: 32  
VIN: 1GB3GRBG6G1322464 License Number: 41494 Bus Number: 162  
Make of Body: Chevrolet Year: 2016 Make of Chassis: Chevrolet Year: 2016  
Bus Type: A1 Mileage: 79106  
Inspection Status: R Inspected By: Joel Flores PE: 7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-3	See Notes: Any defect inspector deems a violation not listed
68-1-3	Reservoir is empty
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.