

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 8/27/2024	<b>Time:</b> 11:43 AM
<b>Name of School Corporation:</b>	BURGE TERRACE CHRISTIAN SCHOOL	<b>Corp ID:</b>
<b>Address of School Corporation:</b>	9345 Brookville Rd	
<b>City:</b> Indianapolis	<b>Zip:</b> 46239	<b>County Number:</b> 49
<b>VIN:</b> 4uzabrdtxecff9773	<b>License Number:</b> 07G5S0	<b>Bus Number:</b> 01
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2013	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2014	<b>Mileage:</b> 90032	<b>PE:</b> 8795
<b>Bus Type:</b> C	<b>Inspected By:</b> Nick Cox	
<b>Inspection Status:</b> O		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
57-1-5	Step-well light is missing or inoperative
29-1-4	Prohibited area line is missing or improper
29-1-5	Prohibited area sign is missing or obscured
59-1-15	See Notes: Any defect inspector deems a violation not listed
65-1-8	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**