

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	9/10/2024	Time:	8:11 AM
Name of School Corporation:	JAY SCHOOL CORPORATION	Corp ID:	383945		
Address of School Corporation:	PO Box 1239				
City:	Portland	Zip:	47371	County Number:	38
VIN:	4UZABRFC9RCUJ6334	License Number:	26371	Bus Number:	45
Make of Body:	Thomas Built Buses, Inc.	Year:	2023	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
62-1-2	One (1) taillight or one (1) brake light does not function
2-1-1	Required back-up lights do not function.
20-1-2	Excessive effort is needed to open the emergency door
7-1-3	Air leak at proper connection
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.