

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	9/11/2024	<b>Time:</b>	8:07 AM
<b>Name of School Corporation:</b>	SOUTHWEST DUBOIS SCH. CORP.	<b>Corp ID:</b>	192110		
<b>Address of School Corporation:</b>	105 W Sunset Dr				
<b>City:</b>	Huntingburg	<b>Zip:</b>	47542	<b>County Number:</b>	19
<b>VIN:</b>	4DRBUSKP0A8235101	<b>License Number:</b>	NBSW10	<b>Bus Number:</b>	10
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	IC Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	111558	<b>Year:</b>	2010
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Philip Lubbers	<b>PE:</b>	7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
7-1-2	ABS warning light is illuminated
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
68-1-1	Washers do not function properly in any manner

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-8	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.