

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/16/2024	Time:	9:45 AM		
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635		
Address of School Corporation:	35 W 3rd St						
City:	Peru	Zip:	46970	County Number:	52		
VIN:	1GB6G3AGXA1168294		License Number:	83999	Bus Number:	Tiger2	
Make of Body:	Starcraft	Year:	2010	Make of Chassis:	Chevrolet	Year:	2010
Bus Type:	A2		Mileage:	147436			
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
50-1-2	The seat belt cutter is not secured using a positive fastening method.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.