

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 9/17/2024 Time: 8:58 AM
Name of School Corporation: SOUTH DEARBORN COMM. SCH. CORP Corp ID: 151600
Address of School Corporation: 6109 Squire Place
City: Aurora Zip: 47001 County Number: 15
VIN: 4UZABRDC78CZ10824 License Number: B595R Bus Number: 9
Make of Body: Freightliner Year: 2008 Make of Chassis: Freightliner Year: 2008
Bus Type: A1 Mileage: 161723
Inspection Status: O Inspected By: Chris Clark PE: 6665

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.