

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/17/2024	Time:	9:39 AM
Name of School Corporation:	SOUTH DEARBORN COMM. SCH. CORP			Corp ID:	151600
Address of School Corporation:	6109 Squire Place				
City:	Aurora	Zip:	47001	County Number:	15
VIN:	4DRBUAAN4CB665162	License Number:	2734	Bus Number:	47
Make of Body:	IC Corporation	Year:	2011	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2012
Bus Type:	C	Mileage:	127447		
Inspection Status:	O	Inspected By:	Chris Clark	PE:	6665

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.