REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		Date:	9/24/2024	Time:	8:31 AM
Name of School Corporation: NC Address of School Corporation:		NORTH DAVIESS CO. COMM. SCHOOL 5494 E SR 58			Corp ID:	141375
City:	Elnora	Zip:	47529		County Number:	14
VIN:	1BAKGCPHOCF288177		License Number:	NBND10	Bus Number:	10
Make of Body:	Blue Bird Corporation	Year: 2011	Make of Chassis:	Blue Bird Corporation	Year:	2012
Bus Type:	С		Mileage:	100783		
Inspection Status:	R	Inspected By:	Philip Lubbers		PE:	7703

Violations - Rejected

Inspection Code	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.