

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	9/24/2024	Time:	9:24 AM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			Corp ID:	141375
Address of School Corporation:	5494 E SR 58			County Number:	
City:	Elnora	Zip:	47529	County Number:	14
VIN:	4UZABRDJ7ACAN3251	License Number:	B143V	Bus Number:	3
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	213012
Inspection Status:	R	Inspected By:	Philip Lubbers	PE:	7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.