REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			**Date:**	9/24/2024	**Time:**	9:07 AM
Name of School Corporation:	HEARTLAND HALL CHILD DEVELOPMENT CHENTER					**Corp ID:**	
Address of School Corporation:	11540 N Meridian Street						
City:	Carmel	**Zip:**	46032			**County Number:**	29
VIN:	1GBJG31U351192409			**License Number:**	B168A	**Bus Number:**	1
Make of Body:	Chevrolet	**Year:**	2005	**Make of Chassis:**	Chevrolet	**Year:**	2005
Bus Type:	A1			**Mileage:**	83846		
Inspection Status:	O	**Inspected By:**	Nick Cox			**PE:**	8795

Violations - Rejected

Inspection Code	Description
41-1-3	There is loose or unprotected wiring in passenger area
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**