REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	10/1/2024	**Time:**	9:22 AM
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			**Corp ID:**	414225
Address of School Corporation:	750 E SR 44				
City:	Franklin	**Zip:**	46131	**County Number:**	41
VIN:	4DRBUAAN69B681470	**License Number:**	31489	**Bus Number:**	105
Make of Body:	IC Corporation **Year:** 2007	**Make of Chassis:**	IC Corporation	**Year:**	2009
Bus Type:	C	**Mileage:**	181457		
Inspection Status:	O	**Inspected By:**	Joel Flores	**PE:**	7415

Violations - Rejected

Inspection Code	Description
59-1-9	There is air leak at the stop arm air bladder that does not affect the air braking system

Violations - Out of Service

Inspection Code	Description
59-2-3	Stop arm does not fully extend to a right angle to the bus

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.