REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		**Date:** 10/1/2024	**Time:**	4:52 PM
Name of School Corporation:	SOUTH PUTNAM COMMUNITY SCHOOLS			**Corp ID:**	676705
Address of School Corporation:	3999 S US 231				
City:	Greencastle	**Zip:**	46135	**County Number:**	67
VIN:	4UZABRDJ98CAW0736		**License Number:** 74707	**Bus Number:**	1003
Make of Body:	Thomas Built Buses, Inc. **Year:** 2010		**Make of Chassis:** Freightliner	**Year:**	2010
Bus Type:	C		**Mileage:** 87546		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.