REPORT OF SCHOOL BUS INSPECTION

Type of 4:52 Post-Crash Inspection Date: 10/1/2024 **Time**: Inspection: РМ SOUTH PUTNAM COMMUNITY SCHOOLS Name of School Corporation: 676705 Corp ID: **Address of School Corporation:** 3999 S US 231 County City: Greencastle Zip: 46135 67 Number: License VIN: 4UZABRDJ98CAW0736 74707 **Bus Number:** 1003 Number: Make of Thomas Built Buses, **Year**: 2010 Freightliner Year: Make of Body: 2010 Inc. Chassis: Bus Type: С Mileage: 87546 Inspected PE: 7008 **Inspection Status:** O Byron Goodman By:

Violations - Rejected

<u>Inspection</u>	Description
<u>Code</u>	<u>Description</u>

The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.