

# REPORT OF SCHOOL BUS INSPECTION

|   |                                  |  |                   |
|---|----------------------------------|--|-------------------|
| <b>Type of Inspection:</b> Semi-Annual                        | <b>Date:</b> 10/2/2024           | <b>Time:</b> 9:16 AM                   |                   |
| <b>Name of School Corporation:</b> HANOVER COMM. SCHOOL CORP. | <b>Corp ID:</b> 454580           |  |                   |
| <b>Address of School Corporation:</b> 14525 Wicker            |                                  |  |                   |
| <b>City:</b> Cedar Lake                                       | <b>Zip:</b> 46303                | <b>County Number:</b> 45               |                   |
| <b>VIN:</b> 4DRBUSKN6BB323845                                 | <b>License Number:</b> 74265     | <b>Bus Number:</b> 17                  |                   |
| <b>Make of Body:</b> IC Corporation                           | <b>Year:</b> 2010                | <b>Make of Chassis:</b> IC Corporation | <b>Year:</b> 2011 |
| <b>Bus Type:</b> C  | <b>Mileage:</b> 171996           |  |                   |
| <b>Inspection Status:</b> O                                   | <b>Inspected By:</b> Tim Grayson | <b>PE:</b> 7558                        |                   |

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

### Inspection Code

### Description

32-2-1      There is fuel leaking from any point on in the fuel system

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**