

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |           |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Semi-Annual                    | <b>Date:</b>           | 10/7/2024      | <b>Time:</b>            | 9:17 AM   |
| <b>Name of School Corporation:</b>    | EVANSVILLE-VANDERBURGH SCH COR |                        |                | <b>Corp ID:</b>         | 827995    |
| <b>Address of School Corporation:</b> | 951 Walnut St                  |                        |                |                         |           |
| <b>City:</b>                          | Evansville                     | <b>Zip:</b>            | 47713          | <b>County Number:</b>   | 82        |
| <b>VIN:</b>                           | 1GBHG31R611143130              | <b>License Number:</b> | 46998          | <b>Bus Number:</b>      | NT1       |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2000           | <b>Make of Chassis:</b> | Chevrolet |
| <b>Year:</b>                          |                                | <b>Year:</b>           |                | <b>Year:</b>            | 2001      |
| <b>Bus Type:</b>                      |                                | <b>Mileage:</b>        | 128349         |                         |           |
| <b>Inspection Status:</b>             | R                              | <b>Inspected By:</b>   | Bradley Miller | <b>PE:</b>              | 7809      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 24-1-2                 | The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description