

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 10/15/2024 **Time:** 10:14 AM
Name of School Corporation: EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725
Address of School Corporation: 941 S Franklin St
City: Oakland City **Zip:** 47660 **County Number:** 26
VIN: 1GB6G3AG8A1165037 **License Number:** 2369 **Bus Number:** 22
Make of Body: Star Trans **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: **Mileage:** 176077
Inspection Status: R **Inspected By:** Bradley Miller **PE:** 7809

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description