REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	10/15/2024	**Time:**	10:14 AM
Name of School Corporation:	EAST GIBSON SCHOOL CORPORATION			**Corp ID:**	262725
Address of School Corporation:	941 S Franklin St				
City:	Oakland City	**Zip:**	47660	**County Number:**	26
VIN:	1GB6G3AG8A1165037	**License Number:**	2369	**Bus Number:**	22
Make of Body:	Star Trans **Year:** 2010	**Make of Chassis:**	Chevrolet	**Year:**	2010
Bus Type:		**Mileage:**	176077		
Inspection Status:	R	**Inspected By:**	Bradley MIller	**PE:**	7809

Violations - Rejected

Inspection Code	Description
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

Inspection Code	Description

Bus Type Description