

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |           |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|-----------|
| <b>Type of Inspection:</b>            | Semi-Annual                    | <b>Date:</b>           | 10/16/2024     | <b>Time:</b>            | 9:46 AM   |
| <b>Name of School Corporation:</b>    | CRAWFORD CO. COMM. SCHOOL CORP | <b>Corp ID:</b>        | 131300         |                         |           |
| <b>Address of School Corporation:</b> | 5808 E Administration Rd       |                        |                |                         |           |
| <b>City:</b>                          | Marengo                        | <b>Zip:</b>            | 47140          | <b>County Number:</b>   | 13        |
| <b>VIN:</b>                           | 1GBJG31K091163308              | <b>License Number:</b> | 81641          | <b>Bus Number:</b>      | 85        |
| <b>Make of Body:</b>                  | Collins Bus Corporation        | <b>Year:</b>           | 2009           | <b>Make of Chassis:</b> | Chevrolet |
| <b>Year:</b>                          | 2009                           | <b>Mileage:</b>        | 149607         | <b>PE:</b>              | 7703      |
| <b>Bus Type:</b>                      | A1                             | <b>Inspected By:</b>   | Philip Lubbers |                         |           |
| <b>Inspection Status:</b>             | R                              |                        |                |                         |           |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                            |
|------------------------|---------------------------------------------------------------|
| 46-1-3                 | Any required padding is missing                               |
| 46-1-5                 | Upholstery or padding is ripped, torn, or improperly repaired |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**