REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection **Date:** 10/16/2024 **Time:** 9:31 AM **Name of School Corporation:** EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1165037License Number:2369Bus Number:22Make of Body:Star Trans Year:2010Make of Chassis:ChevroletYear:2010

Bus Type: Mileage: 176077

Inspection Status: A Inspected By: Bradley Miller PE: 7809

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description