REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 10/21/2024 Time: 11:55 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:1HA3GRBG0HN001263License Number:21795Bus Number:317Make of Body:Chevrolet Year:2017Make of Chassis:Chevrolet Year:2017

Bus Type: A1 Mileage: 93823

Inspection Status: O Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

70-2-1 Any glass or glazing is broken through or missing

8-2-1 There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.