

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 10/21/2024 Time: 5:09 PM
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP. Corp ID: 596155
Address of School Corporation: 501 S Elm St
City: Paoli Zip: 47454 County Number: 59
VIN: 1GB3GSBGOG1138211 License Number: 60889 Bus Number: A6
Make of Body: Chevrolet Year: 2016 Make of Chassis: Chevrolet Year: 2016
Bus Type: A2 Mileage: Unknown
Inspection Status: O Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
33-1-1	The grill has any exposed edges that may cause injury
34-1-1	Any headlight is inoperative
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.