

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/31/2024	Time:	8:56 AM
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.	Corp ID:	414225		
Address of School Corporation:	750 E SR 44				
City:	Franklin	Zip:	46131	County Number:	41
VIN:	4DRBWAAR98A498792	License Number:	74619	Bus Number:	124
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation
Year:	2008	Year:	2008		
Bus Type:	D	Mileage:	117898		
Inspection Status:	O	Inspected By:	Nathan Hampton	PE:	8616

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.