

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 11/1/2024 **Time:** 9:23 AM
Name of School Corporation: EAST GIBSON SCHOOL CORPORATION **Corp ID:** 262725
Address of School Corporation: 941 S Franklin St
City: Oakland City **Zip:** 47660 **County Number:** 26
VIN: 1GB6G3AG8A1145550 **License Number:** 2370 **Bus Number:** 21
Make of Body: Star Trans **Year:** 2010 **Make of Chassis:** Chevrolet **Year:** 2010
Bus Type: **Mileage:** 159305
Inspection Status: **Inspected By:** Bradley Miller **PE:** 7809

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
89-1-3	The strobe light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description