REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	11/6/2024	**Time:**	2:51 PM
Name of School Corporation:	RANDOLPH EASTERN SCHOOL CORP.			**Corp ID:**	686835
Address of School Corporation:	907 N Plum St				
City:	Union City	**Zip:**	47930	**County Number:**	68
VIN:	IBAKFCSHXKF348653	**License Number:**	21860	**Bus Number:**	10
Make of Body:	Blue Bird Corporation **Year:** 2017	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2019
Bus Type:	C	**Mileage:**	65500		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
82-1-2	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
61-1-5	See Notes: Any defect inspector deems a violation not listed
31-1-3	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose

Violations - Out of Service

Inspection Code	Description
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.