

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/6/2024	Time:	2:51 PM		
Name of School Corporation:	RANDOLPH EASTERN SCHOOL CORP.			Corp ID:	686835		
Address of School Corporation:	907 N Plum St						
City:	Union City	Zip:	47930	County Number:	68		
VIN:	IBAKFCSHXKF348653		License Number:	21860	Bus Number:	10	
Make of Body:	Blue Bird Corporation	Year:	2017	Make of Chassis:	Blue Bird Corporation	Year:	2019
Bus Type:	C			Mileage:	65500		
Inspection Status:	O	Inspected By:	Steve Spallinger	PE:	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
61-1-5	See Notes: Any defect inspector deems a violation not listed
31-1-3	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-1	Any glass or glazing is broken through or missing
51-2-1	The service door does not open or close properly
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
63-2-3	Any tire is flat

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.