

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/12/2024	Time:	2:08 PM
Name of School Corporation:	TAYLOR COMMUNITY SCHOOL CORP.	Corp ID:	343460		
Address of School Corporation:	3750 E CR 300 S				
City:	Kokomo	Zip:	46902	County Number:	34
VIN:	4UZAAXDD56CV45220	License Number:	B213Q	Bus Number:	5
Make of Body:	Thomas Built Buses, Inc.	Year:	2005	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	154010	Year:	2006
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
62-1-2	One (1) taillight or one (1) brake light does not function
2-1-1	Required back-up lights do not function.
31-1-3	See Notes: Any defect inspector deems a violation not listed
30-1-3	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
23-1-6	Tailpipe does not extend to, or extends more than 1" beyond the perimeter of the bus body
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.