REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	12/6/2024	**Time:**	9:53 AM
Name of School Corporation:	TRI-COUNTY SCHOOL CORPORATION			**Corp ID:**	918535
Address of School Corporation:					
City:		**Zip:**		**County Number:**	91
VIN:	4DRBUAAN7DB153333	**License Number:**	16573	**Bus Number:**	S6
Make of Body:	IC Corporation **Year:** 2012	**Make of Chassis:**	IC Corporation	**Year:**	2013
Bus Type:	C	**Mileage:**	130109		
Inspection Status:	O	**Inspected By:**	Nathan Hampton	**PE:**	8616

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.