## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:12/17/2024 Time:10:42 AM

Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number: 26VIN:1GB6G3AG8A1145550License Number: 2370Bus Number: 21Make of Body:Star Trans Year: 2010Make of Chassis: ChevroletYear: 2010

Bus Type: Mileage: 162746

Inspection Status: O Inspected By: Bradley Miller PE: 7809

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

8-2-1 There is no brake certification, or the certification has expired or is not signed

**Bus Type Description**