

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Registration **Date:** 12/26/2024 **Time:** 11:15 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP. **Corp ID:** 80750
Address of School Corporation: 2 S 3rd St.
City: Flora **Zip:** 46929 **County Number:** 8
VIN: 1GB3GSB73R1102192 **License Number:** T019398 **Bus Number:** AB6
Make of Body: Chevrolet **Year:** 2023 **Make of Chassis:** Chevrolet **Year:** 2024
Bus Type: **Mileage:** Unknown
Inspection Status: A **Inspected By:** Roger Dickison **PE:** 5586

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description