

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/14/2025 **Time:** 5:25 PM
Name of School Corporation: NORTH PUTNAM COMMUNITY SCHOOLS **Corp ID:** 676715
Address of School Corporation: Box 169
City: Bainbridge **Zip:** 46105 **County Number:** 67
VIN: 4DRBUC8N5JB048531 **License Number:** 17925 **Bus Number:** 2418
Make of Body: IC Corporation **Year:** 2017 **Make of Chassis:** IC Corporation **Year:** 2018
Bus Type: C **Mileage:** 102597
Inspection Status: O **Inspected By:** Byron Goodman **PE:** 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-5	See Notes: Any defect inspector deems a violation not listed
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
11-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.