REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	1/15/2025	**Time:**	1:39 PM
Name of School Corporation:	CLAY COMMUNITY SCHOOLS			**Corp ID:**	111125
Address of School Corporation:	PO Box 169				
City:	Knightsville	**Zip:**	47857	**County Number:**	11
VIN:	4DRBUC8NXLB872091	**License Number:**	23097	**Bus Number:**	69
Make of Body:	IC Corporation **Year:** 2019	**Make of Chassis:**	IC Corporation	**Year:**	2020
Bus Type:	C	**Mileage:**	138749		
Inspection Status:	O	**Inspected By:**	Byron Goodman	**PE:**	7008

Violations - Rejected

Inspection Code	Description
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.