

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/31/2025	<b>Time:</b>	9:54 AM
<b>Name of School Corporation:</b>	TRI-CENTRAL SCHOOLS	<b>Corp ID:</b>	807935		
<b>Address of School Corporation:</b>	2115 W 500 N				
<b>City:</b>	Sharpsville	<b>Zip:</b>	46068	<b>County Number:</b>	80
<b>VIN:</b>	4DRBUAAN88A499693	<b>License Number:</b>	B164S	<b>Bus Number:</b>	6
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2008				
<b>Bus Type:</b>	C	<b>Mileage:</b>	181042		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
37-1-1	The horn does not operate at all
62-1-2	One (1) taillight or one (1) brake light does not function
62-1-1	Any lens is cracked, missing, faded or of the wrong color
46-1-2	Any seat back or bottom is loose
79-1-3	If equipped the emergency warning buzzer does not sound

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
70-2-1	Any glass or glazing is broken through or missing

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**