REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	1/31/2025	**Time:**	9:54 AM
Name of School Corporation:	TRI-CENTRAL SCHOOLS			**Corp ID:**	807935
Address of School Corporation:	2115 W 500 N				
City:	Sharpsville	**Zip:**	46068	**County Number:**	80
VIN:	4DRBUAAN88A499693	**License Number:**	B164S	**Bus Number:**	6
Make of Body:	IC Corporation **Year:** 2007	**Make of Chassis:**	IC Corporation	**Year:**	2008
Bus Type:	C	**Mileage:**	181042		
Inspection Status:	O	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
37-1-1	The horn does not operate at all
62-1-2	One (1) taillight or one (1) brake light does not function
62-1-1	Any lens is cracked, missing, faded or of the wrong color
46-1-2	Any seat back or bottom is loose
79-1-3	If equipped the emergency warning buzzer does not sound

Violations - Out of Service

Inspection Code	Description
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
70-2-1	Any glass or glazing is broken through or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.