

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/7/2025	Time:	10:41 AM
Name of School Corporation:	SCHOOL TOWN OF MUNSTER	Corp ID:	454740		
Address of School Corporation:	8616 Columbia Ave				
City:	Munster	Zip:	46321	County Number:	45
VIN:	1BABJBSA5KF352816	License Number:	22392	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year:	2018	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	73180	Year:	2019
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-7	Non safety related signs/decorations posted.
34-1-1	Any headlight is inoperative
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.