

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/13/2025	Time:	2:33 PM
Name of School Corporation:	LOGANSPORT COMM. SCHOOL CORP.	Corp ID:	90875		
Address of School Corporation:	2829 George St				
City:	Logansport	Zip:	46947	County Number:	9
VIN:	4DRBUSKN1FB664673	License Number:	8414	Bus Number:	1430
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2015
Bus Type:	C	Mileage:	88572		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-3	Any back-up light lens is cracked, broken, faded or missing
20-1-2	Excessive effort is needed to open the emergency door
62-1-1	Any lens is cracked, missing, faded or of the wrong color

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
20-2-2	Door glass is missing
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
7-2-9	There is any defect not in compliance with the minimum school bus brake inspection standards

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.