

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/10/2025	Time:	10:12 AM		
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS		Corp ID:	475075			
Address of School Corporation:	595 Stars Blvd						
City:	Bedford	Zip:	47421	County Number:	47		
VIN:	4DRBUAAN3DB311988		License Number:	5033	Bus Number:	64	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2013
Bus Type:	C		Mileage:	119195			
Inspection Status:	O	Inspected By:	Zach Ruble	PE:	7715		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.