

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/10/2025	Time:	9:57 AM
Name of School Corporation:	LOST RIVER CAREER CO-OP			Corp ID:	596150
Address of School Corporation:	610 Elm St Ste 1				
City:	Paoli	Zip:	57454	County Number:	59
VIN:	1G3HG31F521125340			License Number:	NBLRC1
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	Chevrolet
Bus Type:	A1			Bus Number:	1
Inspection Status:	R	Inspected By:	Philip Lubbers	Year:	2003
				PE:	7703

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
50-1-2	The seat belt cutter is not secured using a positive fastening method.

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.