

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/13/2025	Time:	8:57 AM		
Name of School Corporation:	PERU COMMUNITY SCHOOLS			Corp ID:	525635		
Address of School Corporation:	35 W 3rd St						
City:	Peru	Zip:	46970	County Number:	52		
VIN:	4UZABRFC7RCUD2446		License Number:	25966	Bus Number:	7	
Make of Body:	Freightliner	Year:	2022	Make of Chassis:	Freightliner	Year:	2024
Bus Type:	C		Mileage:	51516			
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.