

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/17/2025	Time:	10:14 AM		
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL		Corp ID:	141375			
Address of School Corporation:	5494 E SR 58						
City:	Elnora	Zip:	47529	County Number:	14		
VIN:	4DRBUC8P8GB138606		License Number:	25600	Bus Number:	ND6	
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	A1	Mileage:	53227				
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
43-1-8	Any required lettering is missing or faded.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.