REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 3/18/2025	**Time:**	10:33 AM
Name of School Corporation:	MANCHESTER COMMUNITY SCHOOLS			**Corp ID:**	858045
Address of School Corporation:	PO Box 308				
City:	North Manchester	**Zip:**	46962	**County Number:**	85
VIN:	1GB3G3BG3D1124112		**License Number:** 19329	**Bus Number:**	31
Make of Body:	Thomas Built Buses, Inc. **Year:** 2012		**Make of Chassis:** Chevrolet	**Year:**	2013
Bus Type:	A2		**Mileage:** 81185		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**