

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/18/2025 **Time:** 10:33 AM
Name of School Corporation: WASHINGTON COMM. SCHOOLS, INC. **Corp ID:** 141405
Address of School Corporation: 301 E South St
City: Washington **Zip:** 47501 **County Number:** 14
VIN: 1GB3GSB71N1176222 **License Number:** 95828 **Bus Number:** A2
Make of Body: Thomas Built Buses, Inc. **Year:** 2022 **Make of Chassis:** Chevrolet **Year:** 2022
Bus Type: A2 **Mileage:** 20550
Inspection Status: O **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
11-1-7	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
11-2-2	A bumper does not meet manufactures specifications
41-2-1	Interior is excessively dirty. (Excessive trash or dirt that would jeopardize the safety of students)
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.