

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                              |                        |            |                         |                       |
|---------------------------------------|------------------------------|------------------------|------------|-------------------------|-----------------------|
| <b>Type of Inspection:</b>            | Re-Inspection                | <b>Date:</b>           | 4/3/2025   | <b>Time:</b>            | 9:40 AM               |
| <b>Name of School Corporation:</b>    | EDINBURGH COMM. SCHOOL CORP. |                        |            | <b>Corp ID:</b>         | 414215                |
| <b>Address of School Corporation:</b> | 202 S Keeley St              |                        |            |                         |                       |
| <b>City:</b>                          | Edinburg                     | <b>Zip:</b>            | 46124      | <b>County Number:</b>   | 41                    |
| <b>VIN:</b>                           | 1BAKBCJA0RF802001            | <b>License Number:</b> | 26642      | <b>Bus Number:</b>      | 17                    |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.     | <b>Year:</b>           | 2023       | <b>Make of Chassis:</b> | Blue Bird Corporation |
| <b>Bus Type:</b>                      | B                            | <b>Mileage:</b>        | 10054      | <b>Year:</b>            | 2024                  |
| <b>Inspection Status:</b>             | A                            | <b>Inspected By:</b>   | Jeff Stone | <b>PE:</b>              | 8184                  |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**