

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 4/10/2025 Time: 11:54 AM
Name of School Corporation: VIGO COUNTY SCHOOL CORPORATION Corp ID: 848030
Address of School Corporation: 3250 Maple Ave
City: Terre Haute Zip: 47804 County Number: 84
VIN: 4DRBWAARXHB691219 License Number: 12466 Bus Number: 1623
Make of Body: IC Corporation Year: 2016 Make of Chassis: IC Corporation Year: 2017
Bus Type: D Mileage: 88241
Inspection Status: O Inspected By: Byron Goodman PE: 7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.