

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/21/2025	<b>Time:</b> 8:59 AM
<b>Name of School Corporation:</b> CENTER GROVE COMM. SCHOOL CORP	<b>Corp ID:</b> 414205	
<b>Address of School Corporation:</b> 4900 W Stones Crossing Rd		
<b>City:</b> Greenwood	<b>Zip:</b> 46143	<b>County Number:</b> 41
<b>VIN:</b> 1GB3GRB77M1251349	<b>License Number:</b> 91292	<b>Bus Number:</b> 204
<b>Make of Body:</b> Collins Bus Corporation	<b>Year:</b> 2021	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2021	<b>Mileage:</b> 47425	<b>Year:</b> 2021
<b>Bus Type:</b>		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Joel Flores	<b>PE:</b> 7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-5	LED type lights have 25% to 49% of the pixels inoperable in any one light

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

<u>Bus Type</u>	<u>Description</u>
-----------------	--------------------