

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|-------------------------|-------------|-------------------------|-----------|
| Type of Inspection: | Annual | Date: | 4/21/2025 | Time: | 9:01 AM |
| Name of School Corporation: | CENTER GROVE COMM. SCHOOL CORP | Corp ID: | 414205 | | |
| Address of School Corporation: | 4900 W Stones Crossing Rd | | | | |
| City: | Greenwood | Zip: | 46143 | County Number: | 41 |
| VIN: | 1HA3GRB79MN010425 | License Number: | 91294 | Bus Number: | 207 |
| Make of Body: | Collins Bus Corporation | Year: | 2021 | Make of Chassis: | Chevrolet |
| Year: | 2021 | Make of Chassis: | Chevrolet | Year: | 2021 |
| Bus Type: | | Mileage: | 47544 | | |
| Inspection Status: | A | Inspected By: | Joel Flores | PE: | 7415 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|