

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/23/2025	Time:	2:58 PM
Name of School Corporation:	EAST NOBLE SCHOOL CORPORATION			Corp ID:	576060
Address of School Corporation:	126 W Rush St				
City:	Kendallville	Zip:	46755	County Number:	57
VIN:	1T88T9E25F1287927	License Number: 8646		Bus Number:	44
Make of Body:	Thomas Built Buses, Inc.	Year:	2014	Make of Chassis:	Freightliner
Bus Type:	D	Mileage:	126502	Year:	2015
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-1	The front bumper does not extend to the edge of the fenders
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.