

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 4/24/2025 **Time:** 3:50 PM
Name of School Corporation: MIDDLEBURY COMMUNITY SCHOOLS **Corp ID:** 202275
Address of School Corporation: 57853 N Ridge Dr
City: Middlebury **Zip:** 46540 **County Number:** 20
VIN: 4UZABRFC1JCJT2832 **License Number:** 19071 **Bus Number:** 40
Make of Body: Thomas Built Buses, Inc. **Year:** 2017 **Make of Chassis:** Freightliner **Year:** 2018
Bus Type: C **Mileage:** 130096
Inspection Status: O **Inspected By:** Joseph Hartman **PE:** 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.