

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Registration	<b>Date:</b>	4/25/2025	<b>Time:</b>	2:39 PM		
<b>Name of School Corporation:</b>	UNION SCHOOL CORPORATION	<b>Corp ID:</b>	686795				
<b>Address of School Corporation:</b>	8707 W US 36						
<b>City:</b>	Modoc	<b>Zip:</b>	47358	<b>County Number:</b>	68		
<b>VIN:</b>	1HA3GRB77RN013654	<b>License Number:</b>	104888	<b>Bus Number:</b>	10		
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2024	<b>Make of Chassis:</b>	Chevrolet	<b>Year:</b>	2026
<b>Bus Type:</b>	B	<b>Mileage:</b>	877				
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Steve Spallinger	<b>PE:</b>	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**