

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/28/2025 **Time:** 9:38 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP **Corp ID:** 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo **Zip:** 47140 **County Number:** 13
VIN: 1GDJG316881231766 **License Number:** 24629 **Bus Number:** 49
Make of Body: GMC **Year:** 2008 **Make of Chassis:** GMC **Year:** 2008
Bus Type: A1 **Mileage:** 183699
Inspection Status: O **Inspected By:** Philip Lubbers **PE:** 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
95-1-15	See Notes: Any defect inspector deems a violation not listed
95-1-10	Does not move smoothly or rest solidly on the ground
59-1-1	The stop arm lights do not flash alternately
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-1	Any stop arm light is inoperative

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.