

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 4/28/2025 Time: 10:52 AM
Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP Corp ID: 131300
Address of School Corporation: 5808 E Administration Rd
City: Marengo Zip: 47140 County Number: 13
VIN: 1GDJG316881231766 License Number: 24629 Bus Number: 49
Make of Body: GMC Year: 2008 Make of Chassis: GMC Year: 2008
Bus Type: A1 Mileage: 183699
Inspection Status: R Inspected By: Philip Lubbers PE: 7703

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
57-1-5	Step-well light is missing or inoperative
95-1-15	See Notes: Any defect inspector deems a violation not listed
95-1-10	Does not move smoothly or rest solidly on the ground
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.